



Incident Reports – Pre-1999

Conveyors

Fatal Accident	MDG 3002, SSAI No. 4	System Safety Accident Investigation Summary - Fatal Accident - Metropolitan Colliery, 2nd April 1992
Survey	MDG 3004 SR 91/1	Inspection Survey of Conveyer Systems in Underground Coal Mines
Accidents	MDG 3004 SR 95/2	Summary of Mine Conveyer Accidents

Fires

Fires Incidents	MDG 3004 SR 95/3	Overview of Mine Fire Incidents in New South Wales Coal Mines, 1989-1995
Compressor Fire	MDG 3002, SSAI No. 5	System Safety Accident Investigation Summary - Fire on a Compressor - Appin Colliery, 26th September 1991 and Code for Air Compressors - Underground

Frictional Ignitions

Frictional Ignitions	MDG 3004 SR 94/1	Review of Reportable Frictional Ignitions of Methane in New South Wales Underground Coal Mines 1987-1998
----------------------	---------------------	--

Injuries & Vibration

Injuries	MDG 3004 SR 2000/2	Strain and Sprain Injury Claims in Surface Coal Operations
Vibration	MDG 3005 VRBI 91/1	Vibration Related Back Injuries to Operator of Mobile Equipment in New South Wales Coal Mines. Includes: Supplementary - Vibration Related Back Injuries to Operator of Mobile Equipment in New South Wales Coal Mines
Vibration	MDG 3005 VRBI 93/1	Whole Body Vibration in Underground Mining

Mobile / Diesel Equipment

Runaway Vehicle	MDG 3002, SSAI No. 1	System Safety Accident Investigation Summary - Westcliffe Colliery, 29th July 1991
LHD	MDG 3002, SSAI No. 2	System Safety Accident Investigation Summary - Oakdale Colliery, 3rd March 1992
MPV	MDG 3002, SSAI No. 3	System Safety Accident Investigation Summary - Newstan Colliery, 26th June 1991
Diesel Exhaust	MDG 3004 SR 2001/1	Report on Diesel Exhaust Analysis Trends in NSW Underground Coal Mines (June 1999-June 2000)
Diesel Exhaust	MDG 3004 SR 2001/2	Report on Diesel Exhaust Analysis Trends in NSW Underground Coal Mines (June 2000-June 2001)
Diesel Exhaust	MDG 3004 SR 2002/1	Report on Diesel Exhaust Analysis Trends in NSW Underground Mines



Pressure Systems

Hydraulic Intensification	MDG 3002, SSAI No. 7	System Safety Accident Investigation Summary – Fatal Accident – Gretley Colliery, 14 th November 1991
Fire extinguisher over-pressurised	MDG 3002, SSAI No. 8	System Safety Accident Investigation Summary – Fatal Accident – Howick Open Cut Mine, 2 nd March
Hydraulic Fluid	MDG 3006 MRT 2	Material Testing for Hydraulic Fluid and Aerosol Products

Tyres

Video: Tyre Safety Awareness Seminar
 Video for persons responsible for haul road design, supervisors responsible for the movement of heavy tyred equipment and shift engineers

Remote Control

Design	MDG 5001	Mine Safety Review Guidelines for the Design of Remote Controlled Mining Equipment
Design	MDG 5001a	Mine Safety Review Assessment Document to Accompany Guidelines for the Design of Remote Controlled Mining Equipment
Use	MDG 5002	Mine Safety Review Guideline for the Use of Remote Controlled Mining Equipment
Use	MDG 5002a	Mine Safety Review Assessment Document to Accompany Guidelines for the Use of Remote Controlled Mining Equipment
Behaviours	MDG 5004	A study of the Risky positioning behaviour of Operators of Remote Control Mining Equipment

Winding Equipment

Winding Incidents	MDG 3004 SR 95/1	Summary of Mine Winder and Shaft Incidents in New South Wales Coal Mines; 1984-1994
Winder Reportables	MDG 3004 SR 2000/1	Coal Mine Winder Reportable Dangerous Occurrences
Winding Incidences	MDG 3004 SR 2001/3	Summary of Mine Winder and Shaft Incidents in New South Wales Coal Mines; 1995-2001
Shaft Sinking	MDG 3006 MRT 1	Test Report Shaft Sinking Winding Apparatus