



SAFETY BULLETIN

Hazardous energy control

BACKGROUND

In recent years fatalities and serious bodily injuries have occurred in the NSW mining industry because of hazardous energy.

Mining Design Guideline *MDG 40 Guideline for Hazardous Energy Control (isolation or treatment)* has been revised and released by the Mine Safety Operations branch of the NSW Department of Primary Industries.

The revised guideline is available online at:

www.dpi.nsw.gov.au/minerals/safety/publications/mdg

RECOMMENDATIONS

All NSW mines should undertake the following:

- Use the revised edition of *MDG 40 Guideline for Hazardous Energy Control (isolation or treatment)* to review and revise isolation procedures
- Review high-risk procedures to ensure that appropriate energy barriers are included to protect people when human error could lead to damaging outcomes.

NOTE: Please ensure all relevant people in your organisation receive a copy of this Safety Bulletin, and are informed of its content and recommendations. This Safety Bulletin should be processed in a systematic manner through the mine's information and communication process. It should also be placed on the mine's notice board.

Signed

Rob Regan
DIRECTOR, MINE SAFETY OPERATIONS BRANCH
NSW DEPARTMENT OF PRIMARY INDUSTRIES

View more safety alerts at www.dpi.nsw.gov.au/minerals/safety/safety-alerts. If you would like to receive safety alerts by email, send your contact details to mine.safetyalert@dpi.nsw.gov.au